

RECEIVED
CENTRAL FAX CENTER
OCT 10 2004

Customer No.: 31561
Application No: 10/604,763
Docket NO.: 11286-US-PA

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application)
Application No.: 10/604,763)
Filed: August 14, 2003)
For: METHOD FOR FABRICATING MEMORY DEVICE HAVING A)
DEEP TRENCH CAPACITOR)

Applicant: Hsu et al.)
Examiner: MALDONADO, Julio J.)
Art Unit 2823)

No fee is believed to be due. However, the Commissioner is authorized to charge any fees required in connection with the filing of this paper to account No. 50-2620 (order No. 11286-US-PA).

RESPONSE TO OFFICE ACTION

U.S. Patent and Trademark Office
Commissioner for Patents
220 20th Street South
Customer Window, Mail Stop Amendment
Crystal Plaza Two, Lobby, Room 1B03
Arlington, Virginia 22202

Dear Sir:

The Office Action mailed on September 9, 2004 has been carefully considered. In response thereto, please enter the following amendments and consider the following remarks.

BEST AVAILABLE COPY

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.